

NEW BALLPARK RENDERINGS



Ballpark Renderings: What's new

Left Field Home Run Porch

The design of the left field Home Run Porch was revised to accommodate two additional sections of seats increasing overall outfield seating capacity. The seating section was revised into a "split" configuration - very similar to the Terrace Level seating sections found elsewhere in the ballpark.

Left Field Light Stand

The single vertical light stand - originally found in left field - has been replaced with a more pleasing light feature atop the main scoreboard (much like the lights found at Coors Field in Denver and Jacob's Field in Cleveland).

Sports Bar

Originally located in left center field; it's been shifted to the building in the left field corner.

Batter's Eye Club

The area formerly known as the Batter's Eye Club in dead center field is being redesigned with a special focus on the creation of an interactive area for kids and families.

Main Twins Ticket Office

Originally located immediately along Seventh Street; it was shifted to the area adjacent to the Sixth Street Plaza.

Primary Twins Team Store

Originally located adjacent to the Sixth Street Plaza; it was moved to the area along Seventh Street.

Right Field "Terrace" Seating

The "terrace" type seating on the Overlook (found in right field) has been replaced with standard ballpark seats.